

Inspector BJ Barbrow

Stormwater Discharge during inspection?

Yes

Condition of Outfalls?

Good condition

Any Leaks or Spills

Hydraulic Line sheared Nov 16th, all hydraulic oil contained beneath plant and cleaned up.

Offsite Tracking

None

BMPs repairs, maintenance, or added?

BMP do not need any adjustments, repairs or additions


Noncompliance issues

None

Tracking/Followup

Comments

I CERTIFY UNDER PENALTY OF LAW THAT THIS DOCUMENT AND ALL ATTACHMENTS WERE PREPARED UNDER MY DIRECTION OR SUPERVISION IN ACCORDANCE WITH A SYSTEM DESIGNED TO ASSURE THAT QUALIFIED PERSONNEL PROPERLY GATHER AND EVALUATE THE INFORMATION SUBMITTED. BASED ON MY INQUIRY OF THE PERSON OR PERSONS WHO MANAGE THE SYSTEM OR THOSE PERSONS DIRECTLY RESPONSIBLE FOR GATHERING THE INFORMATION, THE INFORMATION SUBMITTED IS TO THE BEST OF MY KNOWLEDGE AND BELIEF TRUE, ACCURATE AND COMPLETE.



Larry. W Barbrow. Jr
Safety Environmental Manager