

Quarterly Visual

ACC-New Canton
VAG110048


4th Quarter (Oct-Dec)

On 10/12/2020 at 0.35416666667

Outfall was sampled by BJ Barbrow

Nature of Discharge	Rain
Duration	6:00
Total Rainfall(in)	1.58
Time since previous event (HRS)	>72
Clarity	Clear
Odor	None
Floating Solids	None
Settle Solids	None
Foam	None
Oil Sheen	None
Any other indicators of Storm Water Pollution?	No
Visual quality of the receiving stream?	N/A
Comments and/or corrective actions taken (explain)	<input type="text"/>

I CERTIFY UNDER PENALTY OF LAW THAT THIS DOCUMENT AND ALL ATTACHMENTS WERE PREPARED UNDER MY DIRECTION OR SUPERVISION IN ACCORDANCE WITH A SYSTEM DESIGNED TO ASSURE THAT QUALIFIED PERSONNEL PROPERLY GATHER AND EVALUATE THE INFORMATION SUBMITTED. BASED ON MY INQUIRY OF THE PERSON OR PERSONS WHO MANAGE THE SYSTEM OR THOSE PERSONS DIRECTLY RESPONSIBLE FOR GATHERING THE INFORMATION, THE INFORMATION SUBMITTED IS TO THE BEST OF MY KNOWLEDGE AND BELIEF TRUE, ACCURATE AND COMPLETE.



Larry W. Barbrow Jr.
Safety Environmental Manager